



Reids ■ Playground ■ Maintenance ■ Ltd.

Registered Office: Cabot House, 108 Gipsy Lane, Kettering, Northamptonshire, NN16 8UB.

Telephone / Fax: 01536 601950 **Mobile:** 07785 513600

Email: rpm@reidsplayground.co.uk **Website:** www.reidsplaygroundmaintenance.co.uk

QUOTE RPM/WR/2109

Jane Olds
Fringford Parish Clerk
13 Oak Close
Bicester
OX26 3XD

Date: 21st September 2016

Ref: Fringford Play Area	Cost
1 Bay 2 C/S RPM to replace 2 No. rotten timber uprights with 2 No. 3.6m x 150mm pressure treated timber uprights	£350.00
V Bridge RPM to tension bridge chains	£ 40.00
RPM to replace 2 No. rotten timber uprights with 2 No. 2.4m x 150mm pressure treated timber uprights	£360.00
RPM to cut down 1 No. top support where rot is showing	FOC
RPM to remove 1 No. redundant rotten log	£ 50.00
RPM to smooth off 2 No. cross supports where rot is showing (FOC)	FOC
Stepping Logs RPM to cut the tops off of 5 No. stepping logs where rot is showing	£ 50.00
Swinging Logs RPM to remove 1 No. rotten top log beam and replace with 1 No. new 3.6m x 150mm pressure treated timber balance beam at low level	£350.00
<u>Additional Work (Optional)</u>	
Rubber Mushroom Seats RPM to supply and install 2 No. reconditioned rubber mushroom seats	£150.00
1 Bay 2 F/S RPM to supply and lay 6sqm rubber mulch wear pad under the swing seats	£460.00
All prices quoted are subject to VAT	

■ Specialists in, Maintenance, Installation, On Site Welding and Fabricating

■ Company Registration No: 6249254

■ VAT No: 924 9588 76



Accredited Contractor
www.chas.gov.uk